Make sure to assemble the frame by the numbers on the poles

Poles Connection

Supporting Poles Connection

5 ⬆ 5

Edge Poles Connection

10 10 10

Completed

Without fully tightening the wing nut, install the clamp bars that house the LED light strips. Ensure the threaded holes (shown above in yellow) are facing toward the inside of the display. An even amount of clamp bars should be installed across the top AND bottom of the display. Note that there should be two clamp bars per one light strip.

Once the clamp bars are installed, begin attaching the LED light strips. Each strip has three holes; the middle hole does not need to be used, but the outside holes should have the thumb screws inserted and then attached to the clamp bar as shown below left. When completed, the lights should appear as in the image below right.

After tightening the white thumb screws as well as the wing nuts on the clamp bars to secure the lighting in place, use the short white cords to connect each LED light strip to one another, as shown in the image to the left. Repeat for the display's top light section.

Then, to illuminate the display, connect the long cord from the power supply to the available input on the top section of lights, then the shorter cord from the power supply into the bottom section of lights.

Plug the power supply into the wall or floor outlet.